

5-3-05
12.3.8 v.9

OCT 2004

Work Task: 24820 - 1

Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals



AGC2E000716

Description: Monthly AST (Above-ground Storage Tank) Visual Inspection

Visually inspect the outside of the container for (From SPCC Requirement [40 CFR 112.8(c)(6)]):

- 1. Signs of deterioration
- 2. Signs of Discharges
- 3. Signs of Accumulation of oil inside diked areas

Record finding in Work Order Close Out Comments.

Inspect all vessels on the attached list.

Work Type: 4. Environmental

Work order: 24820 Monthly AST (Above-ground Storage Tank) Visual Inspection

USEPA SF



1263438

Entity to Work On

Number: 710

Name: Common Plant Services

Personnel

Planner: MacVeigh Craig

Supervisor: Parker Sid

Shutdown Information

Shut entity down while work is in progress? No

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

Other Entities to Shut Down

| Number | Name |
|--------|------|
| | |

Time Frame for Completing the Work

Priority: 3 Routine

Start no earlier than: 2004/09/30 06:13:37.00

Finish no later than: 2004/10/21 06:13:37.00

Shutdown period:

Estimated duration:

Planned duration: 4.00 hours

Job Premiums

Job type:

Shift:

Backlog information:

Probability of Satisfaction: High

Material availability: Material not required

Estimated material availability date:

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

Failure Information

Generate failure analysis information: No
 Reason for failure: No Failure Noted
 Root cause:
 Action taken: PM Completed
 Equipment failed due to:
 Entity:
 Catalog item:

Requirements

| Part/Service | Quantity | Item Number | Probability of Satisfaction | Availability | Estimated Material Availability Date | Storeroom |
|--------------|----------|-------------|-----------------------------|--------------|--------------------------------------|-----------|
|--------------|----------|-------------|-----------------------------|--------------|--------------------------------------|-----------|

| Trade | Quantity | Time Required |
|-------|----------|---------------|
|-------|----------|---------------|

| | | |
|--------------|------|------------|
| PM Lube Spec | 1.00 | 4.00 hours |
|--------------|------|------------|

Safety Instructions for this Work

Activities

Seattle Plant

Printed by: Austell Carey
 Printed on: 5/3/2005

Work Task: Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

| Activity Number | Activity | Record Statistics | Record Downtime | Component Movement | Calibration Instrument Used | Comments |
|--------------------------|----------|----------------------|--------------------|-----------------------|--------------------------------|----------|
| <input type="checkbox"/> | | | | | | |
| Processed: | | Processed on: | | Done by: | | |

AGC2E000719

Seattle Plant

Printed by: Austell Carey
Printed on: 5/3/2005